

# Condition Report

---

**LINK OUTDOOR LOUNGE CHAIR**  
FORNASARIG, ITALY

NEEDS SOME LOVE — NOTICEABLE SIGNS OF WEAR.  
IMPERFECTIONS OUTLINED BELOW.



---

**SYDNEY**  
DARLINGHURST

**BRISBANE**  
FORTITUDE VALLEY

**MELBOURNE**  
COLLINGWOOD

**ADELAIDE**  
CBD & SURROUNDS

**ownworld.com.au**